



Basic Weighing & Measurement Equipment Inspection Checklist:

- 1. Check for dirt & debris on top of, underneath, or near the equipment
- 2. Check for standing water, mud or signs of corrosion
- 3. Check for missing parts and pieces
- 4. Check that all wires are in still in place
- 5. Check safety components on heavy capacity equipment
- 6. Check output devices to ensure that they can function properly & without interruption

We can help with your preventative maintenance.

[Contact your nearest Michelli Weighing & Measurement](#) today to schedule a PM service.